

Hard Drive Shredder Power Requirements

Series #	Model #	Horsepower	Voltage	Full Load Amps	Minimum Breaker
Series 1		1.5 HP	120v	20	20
	AMS-150HD		230v - 1 phase	10	20
	AMS-150-SSD		208v - 3 phase	6.9	15
	AMS-150HD-SSD		230v - 3 phase	6	15
			460v - 3 phase	3	15
	AMS-300HD	3 HP	208v - 3 phase	11	20
	AMS-300-SSD		230v - 3 phase	9.6	20
AMS-300HD-SSD	460v - 3 phase		4.8	15	
Hammer Mill	2mm-SSD	7 HP	208v - 3 phase	25.3	50
	4mm-SSD		230v - 3 phase	22	45
	6mm-SSD		460v - 3 phase	11	20
Series 2	AMS-500HD	5 HP	208v - 3 phase	17.5	35
	AMS-500-SSD		230v - 3 phase	15.2	30
	AMS-500HD-SSD		460v - 3 phase	7.6	15
	AMS-750HD	7.5 HP	208v - 3 phase	25.3	50
	AMS-750-SSD		230v - 3 phase	22	45
	AMS-750HD-SSD		460v - 3 phase	11	20
	AMS-1000HD	10 HP	208v - 3 phase	32.2	60
	AMS-1000-SSD		230v - 3 phase	28	60
AMS-1000HD-SSD	460v - 3 phase		14	25	
Series 3	AMS-1500HD	15 HP	208v - 3 phase	48.3	90
	AMS-1500-SSD		230v - 3 phase	42	80
	AMS-1500HD-SSD		460v - 3 phase	21	40
	AMS-2000HD	20HP	208v - 3 phase	62.1	100
	AMS-2000-SSD		230v - 3 phase	54	90
	AMS-2000HD-SSD		460v - 3 phase	27	60
E-Scrap	AMS-PT4040	80 HP	208v - 3 phase	240	350
			230v - 3 phase	208	300
			460v - 3 phase	104	180
	AMS-PT5050	100 HP	208v - 3 phase	300	400
			230v - 3 phase	260	400
			460v - 3 phase	130	200